




Annual Inspection Report		Page No. 1 of 1	
<i>Inspection and report meeting the requirements of Part 257.84(b)</i>			
Merrimack Station Ash Landfill	Location: Bow, New Hampshire	Year: 2017	File No. 2025.06
Date of Inspection:	January 8, 2018	Volume of CCR in place: 204,000 cubic yards	
Completed by:	Lisa Damiano, P.E.		
Changes in landfill geometry since previous annual inspection? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> <i>If yes, please explain below.</i>			
Observed actual/ potential structural weakness? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> <i>If yes, please explain below.</i>			
Observed existing conditions that are disrupting/could disrupt the operation and safety of the facility? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> <i>If yes, please explain below.</i>			
Other Observations:			
<ul style="list-style-type: none"> • Steep slope observed at the active face of the landfill. If the slope failed, CCR would slide into existing empty lined cell. We recommend reducing the slope for safety of operators. • The leachate collection and storage system was observed to be in good operating condition. • Perimeter fence was secure and in good condition. 			
Review of available information regarding the status and condition of the landfill:			
Weekly Inspection Forms:			
Any stability, operation, or safety issues reported? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> <i>If yes, please explain below.</i>			
Previous Annual Inspection Reports:			
Any stability, operation, or safety issues reported? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> <i>If yes, have the issues been addressed?</i>			
<p><i>Steep slope observed at the active face of the landfill. Sanborn Head performed an Interim Slope Stability Evaluation, dated 2/29/2016 and concluded that the slope was likely stable for interim conditions. However, to reduce the potential for instability, we recommended that the slope be flattened such that the inclination approaches 2H:1V or flatter. The slope modification has not been completed at this time.</i></p> <p><i>Limited woody vegetation observed growing near the location of the anchor trench during January 2017 inspection. Vegetation was removed during January 2017 and May 2017.</i></p>			
Signature:	Date: 1/8/2018	Attachments:	
		<input type="checkbox"/> None <input checked="" type="checkbox"/> Site Photographs <input type="checkbox"/> Field Sketch <input type="checkbox"/> Other	
Reviewed By:	Date: 1/8/2018		
			

ANNUAL INSPECTION PHOTOGRAPHS



Photo 1: Active cell of the landfill with steep slope at working face.



Photo 2: Active cell of the landfill with steep slope at working face.



Photo 3: Stable and established slopes in inactive capped area of landfill.



Photo 4: Landfill cells not currently in use.